# INSTALLATION RECORD

| AIRPLANE | LOCATION | DATE INSTALLED | TOTAL HOURS AT INSTALLATION | DATE REMOVED | TOTAL HOURS AT REMOVAL | AGENCY CERT. NO. |
|---|---|---|---|---|---|---|
| N626C | M-38 | 4/15/16 | 1019 | 7/15/15 | 1035 | |

LOG ENTRY - PUT IN TOTAL TIME

7/23/15 Franklin 6A4-165-B3 Total time 1035 SMOH 0 Engine disassembled for overhaul. Crankshaft yellow tagged by Aircraft Specialties. Rod and main ground .010. Crankcase yellow tagged by Divco. All internal steel yellow tagged by Aircraft Specialties. Replaced cylinder liners, valve guides, valve seats, valve springs, piston rings, and hardware. Exhaust valves replaced with new old stock 18285 valves. New gaskets and bearings used for reassembly. Magnetos overhauled by Velocity Shoppe, Timing set to 32 deg. Generator repaired with new oil seal. Installed new Skytec Starter. Engine test run 4hours, all temps and pressure within limits. Cylinder compressions #1/72, #2/70, #3/74, #4/74, #5/73, #6/70. All work performed in accordance with the Franklin 165 maintenance manual. Oil drained for shipping. [signature] AP3120694