

## Stinson Airframe Log Write-up

Removed all fabric, cleaned and refinished all parts of the airframe, removed all old paint. Recovered wings and fuselage with Stits Poly Fiber process in accordance with STC SA1008WE. Repainted all metal parts with Stits matching paint. Installed new o-rings in landing gear shocks, installed new o-rings in brake cylinders and wheels, installed new brake linings. All engine gage instruments overhauled by certified repair shop. (Documentation on hand). Rewired complete airframe. Checked and lubricated all pulleys, control cables and controls. Checked all lights for operation. Removed Narco MK-III radio and installed King KX-155, KI-209 VOR/GS, KMA-20 Audio, KT-76 Transponder, AR-850 encoder, King KLN-35 GPS.