

Aircraft Record General Information

Manufacturer CONSOLIDATED VULTEE Model STINSON 108-3
Serial 3626 Registration Number NC626C
Date of Manufacture 1947

Engine(s) currently installed:

Manufacturer FRANKLIN Model 6A1-165-B3 Serial 30901
Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer MCCOULEY Model FIXED PITCH 1A170
HUB Model DEB-18170-7635 Serial 54973 ^{PMF} Serial 1A170
~~Blade Model~~ HUAL-DAT-7653PMF Serial _____ Serial _____ Serial _____
Blade Model 1A170 Serial _____ Serial _____ Serial _____

BEACON INSTALLED. BEACON ID 20088 ^{PMF} ~~A8536~~ A8536
FFBFF



Repairs and Alterations

ing and Certificate Number of
pages for other specific entries.)

RIVETS AND
 DROPPED MAIN GEAR
 GEAR STRUTS,
 OILED, REFINISHED.
 WHEELS, CHECKED
 ON, RE-ASSEMBLED.
 WHEEL ATTACH
 INSTALLED LANDING
 GEAR WITH NEW MAIN
 GEAR ALIGNMENT
 ON FUSILAGE,
 MAIN AILERONS COVERED
 IN ACCORDANCE WITH
 STINSON 108-3,
 PAR 243 OF POLY-
 COATING PROCEDURE
 SECTION NO 21 (DATE)
 COMPLETED →

YEAR 20 16	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE 2016 19/8	95.12	-	2387	SEPTEMBER 2006, ALL RE-FINISHING DONE IAW ORIGINAL POLY-FIBER AIRCRAFT COATINGS COLORS AND TRIM IN STINSON RED (POLY-FIBER COLOR 197 AND POLY-FIBER TRIM COLOR 131). INSTALLED NEW LEATHER INTERIOR, VINYL HEADLINER AND NEW CARPETS. TEST DATA ON HAND FOR BORN TESTS. INSTALLED KING KX-155 NAV/COM WITH KI-209 HEAD, KLN-35 KING GPS, KING KMA-20 AUDIO PANEL, KING KT-76A TRANSPONDER WITH AR-850 ALTITUDE ENCODER. ALL WIRING IN ACCORDANCE WITH REQUIREMENTS OF AC 43-13-2A, PARAGRAPHS 21, 22, 23, 27 AND FIGURE 2.2 SYSTEMS WERE → CONTINUED →

Tests, Repairs and Alterations

Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

CHECKED OIL,
 T AND BALANCE
 ED AIRCRAFT
 WITH AC13-B-18,
 MEASURED FUEL
 LIMITS. WEIGHT
 OF FUEL IS
 CHECKED NEW
 2 E04 FLT,
 MS ARE CHECKED
 ON THIS DATE.
 WITH. SEE LIST IN REAR
 M. Luther
 12485360 IA
 2016

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11/10/2016	96.31	-	2508 2390.19	Checked All CONTROL CABLES AND PULLIES. LUBRICATED AS REQ'D. Checks etc. Checked BATTERY BOX DRAIN SYSTEM, etc. Checked ELI JAW FAR 91.207(d). INSTALLED NEW REBAT BATTERY. Checked CONTROL COLUMN ATTACH POINTS AND OPERATION, etc. INSTALLED NEWLY OVERHAULED TURN & BANK, ARTIFICIAL HORIZON, ALT METER. INSTRUMENTS OVERHAULED BY KEYSTONE INSTRUMENT SERVICES. INSTALLED NEW DG. CHECKED SEAT ATTACH POINTS AND LOCKS. INSTALLED NEW FUEL TANK CAPS FROM UNIVAIR. CHECKED LANDING GEAR ATTACH POINTS AND WHEELS AND BRAKES.

Tests, Repairs and Alterations

Rating and Certificate Number of
 Check pages for other specific entries.)

WHEELS IN BRAKES.
 DISKS AND
 CHECK FABRIC
 POINTS AND SEAMS,
 PULLIES. CHECKED
 WIRE FOR INTEGRITY,
 INTERIOR FUSelage
 CONTROL CABLES, LINKS,
 VISUALLY, OK.
 COMPLIED WITH.
 THIS A/C HAS BEEN
 IN ACCORDANCE WITH
 SECTION PROCEDURES
 FOUND AIR WORTHY.
 LISTED WITH AS LISTED
 AT BACK OF BOOK
 PETER AEPH128530 EA

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations <small>Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)</small>
	97.79	-	2391.77	CHECKED ALL FABRIC ATTACH POINTS AND SEAMS - OK. CHECKED TRAIL STRUCTURE AND ATTACH POINTS, OK. CHECKED INTERIOR FUSelage STRUCTURE AND CONTROL CABLES, LINKS, ATTACK POINTS AND FOUND OK. SERVICED HYDRAULIC BRAKES, TOPPED OFF FLUID. CHECKED BRAKE DISKS AND PUCKS, OK. CHECKED AND LOBED ALL CONTROL CABLE PULLIES. CHECKED BATTERY BOX DRAIN SYSTEM AND FOUND CLEAR. CHECKED ELT IAW FAR 91.207(d) AND FOUND OK. SERVICED BATTERY AND TOPPED OFF CHARGE. CHECKED CONTROL COLUMN AND PEDAL ATTACH POINTS AND FOUND OK. - SEE NEXT PAGE -

Tests, Repairs and Alterations

Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

AD INSTRUMENT FOR SECURITY. CHECKED SEAT BELTS, OK. CHECKED ATTACH POINTS. CYLINDERS. CHECKED FOR CRACKS, VALVES TO CORRECT PRESSURE. CHECKED ALL ADS (SEE LOG). ALL ADS HAVE BEEN CHECKED WITH ~~LAST~~ ^{NEW} ADSB. THIS AIRCRAFT MAINTAINED IN ACCORDANCE WITH SECTION PROCEDURES AND AIRWORTHY. COMPLIED WITH ASB BOOK

YEAR 20 <u>20</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12/22	97.79		2391.77	<p>INSTALLED ADSB UNIT WITH IDENTIFICATION ZDC88-A8536-FFBFF. SET UP UNIT FOLLOWING INSTRUCTIONS AND FOUND CODES AND TRANSMISSION TO MEET REQUIREMENTS ON GROUND TESTS. REGISTRATION EXPIRES AUGUST 31, 2022.</p> <p>7</p> <p>- ALL SYSTEMS HAVE BEEN CHECKED AS OF THIS DATE AND HAVE BEEN FOUND AIRWORTHY</p> <p>- R.R. LUTHEVAER/IA DEC. 22, 2020 -</p> <p>NO A12485360</p>

